

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Acura	CSX	08-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Acura	ILX	13-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5513	7000K	VS70	OBDII required
Acura	ILX	16-18	7007HP		5514	7000K	VS70	Auto-relearn
Acura	ILX	19-22		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	Integra (snap-in)	23-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	Integra Type S	24		5003' (Program first)	3751	7000K	VS70	Auto-relearn
Acura	MDX	04-06	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	MDX	07-13	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	MDX	14-15			5512	7000K	VS70	Auto-relearn
Acura	MDX	16-20	7007HP		5514	7000K	VS70	Auto-relearn
Acura	MDX	22-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	NSX	16-22		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	RDX	07-12	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	RDX	13-15			5512	7000K	VS70	Auto-relearn
Acura	RDX	16-18	7007HP		5514	7000K	VS70	Auto-relearn
Acura	RDX (clamp-in)	19-21		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	RDX (snap-in)	21-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	RL	05-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	RL	09-12	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Acura	RLX	14-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	RLX	16-20			5512	7000K	VS70	Auto-relearn
Acura	TL	06-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Acura	TL	09-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	TLX	15-17	7007HP		5514	7000K	VS70	Auto-relearn
Acura	TLX	18-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Acura	TLX	21-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Acura	TSX	07-14	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Acura	ZDX	10-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1214	2045K	NO	Auto-relearn
Acura	ZDX	24			3166	VS20	VS20	Auto-relearn
Alfa Romeo	4C	15-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Alfa Romeo	8C Competizione	09-10		5003 (Program first)	9001	1090K	1092 or 1094	
Alfa Romeo	Giulia	17-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Stelvio	18-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7000K	VS70	Auto-relearn
Alfa Romeo	Tonale	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Aston Martin	DBX	21-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Trigger required
Aston Martin	Vantage	19-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Audi	Allroad	02-05		5003 (Program first)	9004	1090K	1092 or 1099L	No tools needed
Audi	A3	08-11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A4	05-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A4 cabrio	09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A4 4-door	09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A5	08-09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	A6	05-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	A6 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	A7 (clamp-in)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	A8	02-03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	A8	04-09		5003 (Program first)	9001	1090K	1092	No tools needed
Audi	A8 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	e-tron crossover (clamp-in)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	e-tron GT sedan	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	Q5	09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	Q7	07-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	Q7 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	Q8 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	Q8 e-tron	24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	R8	08-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	R8	10-23		5003 (Program first)	9011	1096	1096	No tools needed
Audi	RS3	17-20		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS3	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS4	07-08		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	RS5	18-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS6	03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	RS6	21-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS7	14-18		5003 (Program first)	9011	1096	1096	No tools needed
Audi	RS7	21-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS e-tron GT	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	RS Q8	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S4	05-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	S5	08-09	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	S6	07-09		5003 (Program first)	9011	1090K	1092	No tools needed
Audi	S6 (clamp-in)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S7 (clamp-in)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	S8	02-03		5003 (Program first)	9004	1090K	1092	No tools needed
Audi	S8	07-09		5003 (Program first)	9001	1090K	1092	No tools needed
Audi	S8	16-18		5003 (Program first)	9011	1096	1096	No tools needed
Audi	S8	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	SQ5	14-16		5003 (Program first)	9011	1096	1096	No tools needed
Audi	SQ7 (clamp-in)	22-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	SQ8 (non-RS)	22-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Audi	TT	08-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1053	1030K	NO	Trigger required
Audi	TT RS	18-22		5001 (Program first) or 5003 (Program first)	9018	1096	1096	No tools needed
Bentley	Arnage	02-03		5003 (Program first)	9001	1090K	1092-1095	
Bentley	Arnage	04-09		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Azure	07-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Bentayga	17-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Brooklands Coupe	08-09		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	04-05		5003 (Program first)	9001	1090K	1092-1095	
Bentley	Continental GT (Post May 2005)	05-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Continental GT	11-18		5003 (Program first)	9011	1096	1096	
Bentley	Continental GT	20-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Flying Spur	06-10		5003 (Program first)	9011	1090K	1092-1095	
Bentley	Flying Spur	11-18		5003 (Program first)	9011	1096	1096	
Bentley	Flying Spur	20-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	
Bentley	Mulsanne	11-20		5003 (Program first)	9011	1096	1096	
BMW	1 Series	08-11		5003 (Program first)	1027	1090K	1092-1095	No tools needed
BMW	1 Series (Post Sept. 2010)	11-13		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
BMW	2 Series	14		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	2 Series 2dr (Post March 2014)	14-21	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	2 Series (4dr)	20-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	2 Series (2dr)	22-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	3 Series	02-06		5003 (Program first)	9002	1090K	1092-1095	No tools needed
BMW	3 Series	07-09		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	3 Series	10-11		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	3 Series 2dr. and Wagon	12-13		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	3 Series 4dr. Sedan	12-14		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	3 Series (Post March 2014)	14-18	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series Gran Turismo	19	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series wagon	19	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	3 Series sedan (non-M3)	19-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	4 Series	14		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	M4 GTS	15-17		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	4 Series (Post March 2014)	14-20	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	4 Series and M4	21-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	5 Series	06-11		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	5 Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	5 Series (Post March 2014)	14-16		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	5 Series Gran Turismo	17		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	5 Series	17-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	6 Series	06-10		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	6 Series	12-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	6 Series (non-G.T.)	14-19		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	6 Series Gran Turismo	18-19		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	7 Series	02-05		5003 (Program first)	9002	1090K	1092-1095	No tools needed
BMW	7 Series	06-11		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	7 Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	7 Series (Post March 2014)	14-15		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	7 Series	16-22		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	7 Series	23-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	8 Series	19-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	i3	14-21	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	i4 and M	22-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	i5	24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	i7	23-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	i8	14-20	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	iX and M	22-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	M3	21-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	M4	21-22		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X1	13-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	X1	15		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	X1	16-22	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	X1	23-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	X2	18-23	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	X3	06-10		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	X3	11-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	X3	15-17		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	X3	18-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X4	15-18		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	X4	19-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X5	07-11		5003 (Program first)	1027	1090K	1092-1095	No tools needed
BMW	X5 (Post Oct. 2010)	11-13		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	X5	14-18	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	X5	19-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X5	24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	X6	08-11		5003 (Program first)	1027	1090K	1092-1095	No tools needed
BMW	X6 (Post Oct. 2010)	11-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	X6	15-19	7008HP	5001 (Program first) or 5003 (Program first)	5256	7020K	VS70	No tools needed
BMW	X6	20-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X7	19-22		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
BMW	X7	23-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	X7	23-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
BMW	Z Series	07-11		5003 (Program first)	1027	1090K	1091-1095	No tools needed
BMW	Z Series (Post Sept. 2010)	11-14		5001 (Program first) or 5003 (Program first)	9012	1096	1096	No tools needed
BMW	Z4	15-16		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
BMW	Z4	19-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
** Note: 1099 and 1099L are valve options on some special wheel packages.								
Buick	Allure	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Buick	Allure	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Cascada	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Enclave	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Buick	Enclave	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Enclave	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Buick	Enclave	18-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Buick	Encore	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Encore	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Buick	Encore GX	20-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Buick	Envision	16-18	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Buick	Envision	19-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Buick	Envision	21-23		5003 (Program first)	3166*	VS950	VS950	Auto-relearn
Buick	Envista	24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Buick	LaCrosse	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Buick	LaCrosse	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	LaCrosse	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Buick	LaCrosse	17-19	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Buick	Lesabre	07	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Lucerne	07-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Rainier	06-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Buick	Regal	11-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Regal	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Buick	Regal and TourX	18-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Buick	Verano	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Buick	Verano	16-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Cadillac	ATS	13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	VS90	VS90	Trigger required
Cadillac	ATS	14-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ATS (snap-in)	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Cadillac	ATS Performance	13	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	Discontinued	7020K	VS70	Trigger required
Cadillac	ATS Performance	14-15	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	ATS Performance	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Cadillac	ATS-V	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Cadillac	CT4	20-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	CT4-V	20-24		5003 (Program first)	8424	2030K	VS40	Auto-relearn
Cadillac	CT5	20-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	CT5-V	20-24		5003 (Program first)	8424	2030K	VS40	Auto-relearn
Cadillac	CT6	16-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Cadillac	CT6 and V	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Cadillac	CT6-V	19-20	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
Cadillac	CTS	04-07	7001HP or 7007HP	5002' (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Cadillac	CTS	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	CTS	16-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Cadillac	CTS Vsport	14-15	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	CTS Vsport	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Cadillac	CTS-V	09-15	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	CTS-V	16-19	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Cadillac	Deville	01-05		5002' (Program first) or 5003 (Program first)	9117	1080K	NO	Trigger required
Cadillac	DTS	06	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	DTS	07-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ELR	14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	ELR	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Cadillac	Escalade	04		5002 (Program first) or 5003 (Program first)	9115	1070K	NO	Trigger required
Cadillac	Escalade	05-06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
Cadillac	Escalade	07	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	Discontinued	2020K	NO	Trigger required
Cadillac	Escalade	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	Escalade	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	Escalade	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Cadillac	Escalade	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Cadillac	Escalade	21-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Escalade Trailer TPMS	21-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
Cadillac	Lyriq with 20in OE wheels	23-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	Lyriq with 22in OE wheels (rear-facing sensor)	23-24		5003 (Program first)	NEW	2030K	NEW	Auto-relearn
Cadillac	Seville	01-04		5002 (Program first) or 5003 (Program first)	9117	1080K	NO	Trigger required
Cadillac	SRX	04-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Cadillac	SRX	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	STS	05-08	7001HP	5002 (Program first) or 5003 (Program first)	9076	1070K	NO	Trigger required
Cadillac	STS	09-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	STS-V	09	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Cadillac	XLR	04-09	7001HP	5002 (Program first) or 5003 (Program first)	9076	1070K	NO	Trigger required
Cadillac	XT4	19-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XT4	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Cadillac	XT5	17	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Cadillac	XT5	18-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XT6	20-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Cadillac	XTS	13-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Cadillac	XTS	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Avalanche	06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Avalanche	07	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Avalanche	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Avalanche	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Aveo	08-11		5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	OBDII required
Chevrolet	Blazer	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Blazer EV	24		5003 (Program first)	3166	VS20	VS20	Trigger required
Chevrolet	Bolt	17-18	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Bolt	19-21	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Bolt and EUV	22-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Camaro	10-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Camaro	16-19	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Camaro	20-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Camaro (V8)	12-15	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Camaro (V8)	16-19	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Camaro (V8)	20-24	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Caprice	11-13	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Caprice	14-17	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Chevrolet	Captiva	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	City Express	15-18	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Chevrolet	Cobalt (snap-in)	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Cobalt (clamp-in)	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Cobalt SS	10	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Colorado	07-12	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Chevrolet	Colorado	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Colorado	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Colorado	20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Colorado	21-22			2346	VS20	VS20	Auto-relearn
Chevrolet	Colorado	23-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Corvette (C5)	97-00			8006	1077K	NO	Trigger required
Chevrolet	Corvette (C5)	01-04		5002' (Program first) or 5003 (Program first)	9117	1080K	NO	Trigger required
Chevrolet	Corvette (C6)	05-09	7001HP	5002' (Program first) or 5003 (Program first)	9076	1070K	NO	Trigger required
Chevrolet	Corvette (C6)	10-13	7001HP or 7007HP	5002' (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Corvette (C7)	14-19		5001 (Program first) or 5003 (Program first)	NEW	2030K	VS40	Auto-relearn
Chevrolet	Corvette (C8)	20-24		5003 (Program first)	8424	2030K	VS40	Auto-relearn
Chevrolet	Cruze	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Cruze Limited (315MHz)	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Cruze	16-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Cruze	19	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Equinox	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Equinox	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Equinox	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Equinox	18-21	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Equinox	22-24	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	2346	VS20	VS20	Trigger required
Chevrolet	Equinox EV	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Express Series	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Express 1500	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Express 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Express 2500/3500	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Chevrolet	Express 2500/3500 SRW	17-24	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	HHR	08-10	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	HHR	08-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala	06-07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Impala	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	14-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Impala (new)	16-20	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (clamp-In)	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Chevrolet	Malibu	08-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Malibu (non-turbo)	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Malibu (turbo or Hybrid)	16-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Malibu	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Monte Carlo	05-07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Monte Carlo	07	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Orlando	12-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Silverado	18	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado LD (old)	19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado 1500	19-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado 1500 LTD	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado 1500 (facelifted)	22-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Silverado 2500/3500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Silverado 2500/3500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Silverado 2500/3500	18-19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Silverado HD (SRW)	20-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Silverado HD (SRW)	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Silverado 3500HD DRW (Front alloy wheel)	20-23		5001 (Program first) or 5003 (Program first)	7659	DA543E	DA543E	Trigger required
Chevrolet	Silverado 3500HD DRW (Front alloy wheel)	24		5003 (Program first)	7624	DA543E	DA543E	Trigger required
Chevrolet	Silverado 3500HD DRW (Front steel wheel)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Front steel wheel)	24		5003 (Program first)	8424	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Rear wheels)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
Chevrolet	Silverado 3500HD DRW (Rear wheels)	24		5003 (Program first)	8424	2030K	VS40	Trigger required
Chevrolet	Silverado Trailer TPMS	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
Chevrolet	Sonic	12-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Sonic	16-20	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Spark	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Spark	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	SS sedan	14	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	SS sedan	15-17	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	2030K	VS40	Trigger required
Chevrolet	Suburban	04		5002 (Program first) or 5003 (Program first)	9115	1070K	NO	Trigger required
Chevrolet	Suburban	05-06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Suburban 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Suburban 1500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Suburban 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Suburban 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Suburban 2500	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Suburban	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Suburban	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Suburban	21-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Tahoe	04		5002 (Program first) or 5003 (Program first)	9115	1070K	NO	Trigger required
Chevrolet	Tahoe	05-06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
Chevrolet	Tahoe	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	2020K	NO	Trigger required
Chevrolet	Tahoe	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Tahoe	07-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Tahoe	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
Chevrolet	Tahoe	21-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Trailblazer	06-09	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Chevrolet	Trailblazer	21-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Trailer TPMS	21-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
Chevrolet	Traverse	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Traverse	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Traverse	18-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Traverse	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Chevrolet	Trax	15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Trax	16-22	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Trax	24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
Chevrolet	Uplander	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Chevrolet	Volt	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Chevrolet	Volt	16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
Chevrolet	Volt	17-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
Chevrolet	Volt	19	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Auto-relearn
Chrysler	200	11-14	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Chrysler	200 sedan	15-16	7008HP	5001 (Program first) or 5003 (Program first)	5775	VS90	VS90	Auto-relearn
Chrysler	200	17	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	300M	02-04	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Chrysler	300	05-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	300	08	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Chrysler	300	09		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Chrysler	300	10-21		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Chrysler	300	22-23		5001 (Program first) or 5003 (Program first)	7472	1096	1096	Auto-relearn
Chrysler	300C SRT8	10-14		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Chrysler	Aspen	07-09	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Chrysler	Crossfire	04-08			9028	1080K	NO	Dealer OBD only
Chrysler	Grand Caravan (Canadian)	21-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	Pacifica (433 MHz)	04	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Chrysler	Pacifica (315 MHz)	04-05	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1052	1050K	NO	Auto-relearn
Chrysler	Pacifica	06-08	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	Pacifica	17-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Chrysler	Prowler	01			8004	1077K	NO	Dealer OBD only
Chrysler	Prowler	02			9028	1080K	NO	Dealer OBD only

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.
 Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
 Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Chrysler	PT Cruiser	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1051	1050K	NO	Auto-relearn
Chrysler	Sebring	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Chrysler	Sebring	10	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Chrysler	Town and Country	02-03	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Chrysler	Town and Country	04-05	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1052	1050K	NO	Auto-relearn
Chrysler	Town and Country	06-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1051	1050K	NO	Auto-relearn
Chrysler	Town and Country	08-10	7004		1043	1050K	NO	Auto-relearn
Chrysler	Town and Country	10	7004		1043	7000K	VS70	Auto-relearn
Chrysler	Town and Country	11-16		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Chrysler	Voyager	20-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Avenger	08-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Avenger	11-14	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Dodge	Caliber	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Caliber	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Dodge	Caravan	04-05	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1052	1050K	NO	Auto-relearn
Dodge	Caravan	06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1051	1050K	NO	Auto-relearn
Dodge	Challenger SRT8	08-14		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	09		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger	10-21		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Challenger	22-23		5001 (Program first) or 5003 (Program first)	7472	1096	1096	Auto-relearn
Dodge	Challenger 6.4L V8	15-21		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Challenger Hellcat / Demon	15-21		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger	06-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Charger	08	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Charger	09		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger SRT8	10-14		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger	10-21		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Charger	22-23		5001 (Program first) or 5003 (Program first)	7472	1096	1096	Auto-relearn
Dodge	Charger 6.4L V8	15-21		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Charger Hellcat	15-21		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Dodge	Dakota	08-10	7001HP or 7007HP		9154	9066K	9066K	Auto-relearn
Dodge	Dakota	11	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	9308	VS950	VS950	Auto-relearn
Dodge	Dart	13-16	7008HP	5001 (Program first) or 5003 (Program first)	5775	VS90	VS90	Auto-relearn
Dodge	Durango	07-09	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Dodge	Durango	11-15		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Durango	16	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS90 or VS20	VS90 or VS20	Auto-relearn
Dodge	Durango	17-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Durango SRT	18-24	7008HP	5001 (Program first) or 5003 (Program first)	2495	7020K	VS70	Auto-relearn
Dodge	Grand Caravan	02-03	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Dodge	Grand Caravan	04-05	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1052	1050K	NO	Auto-relearn
Dodge	Grand Caravan	06-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1051	1050K	NO	Auto-relearn
Dodge	Grand Caravan	08-10	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Grand Caravan	10	7004	5001 (Program first) or 5003 (Program first)	1043	7000K	VS70	Auto-relearn
Dodge	Grand Caravan	11-20		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Hornet	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Dodge	Journey	09-10	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Journey	11-20		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Magnum	05-07	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Dodge	Magnum	08	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Nitro	07-09	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Dodge	Nitro	10-11	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Dodge	Ram 1500	08			9154	9066K	9066K	Auto-relearn
Dodge	Ram 1500 (Siemens)	09	7004	5001 (Program first) or 5003 (Program first)	1043	1050K	NO	Auto-relearn
Dodge	Ram 1500 (Schrader)	09	7004	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Dodge	Ram 2500	08-09	7001HP		9154	9066K	9066K	Auto-relearn
Dodge	Ram	10-13		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Dodge	Sprinter (SRW)	07-10		5002 (Program first) or 5003 (Program first)	1042	1098K	1098K	Trigger required
Dodge	Viper	03-10			9028	1080K	NO	Dealer OBD only
Dodge	SRT Viper	13-17		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Ferrari	296	22-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
Ferrari	F430	05-07		5003 (Program first)	9001	1090K	1092	No tools needed
Ferrari	F430 (Post July 2007)	07-09		5003 (Program first)	9011	1090K	1092	No tools needed
Ferrari	458	10-15		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	488	16-20		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	575M (433 MHz)	02-05		5003 (Program first)	9001	1090K	1092	No tools needed
Ferrari	575M (315 MHz)	02-05		5003 (Program first)	9004	1090K	1092	No tools needed
Ferrari	599	07-11		5003 (Program first)	9001	1090K	1092	No tools needed
Ferrari	612 Scaglietta	05-10		5003 (Program first)	9001	1090K	1092	No tools needed
Ferrari	812	18-22		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Ferrari	California	09-10		5003 (Program first)	9011	1090K	1092	No tools needed
Ferrari	California	11-18		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	Enzo	03-05			9005	1090K	1092	
Ferrari	F8	20-22		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Ferrari	F12	13-17		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	FF	12-16		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	FXX	05-06			9005	1090K	1092	
Ferrari	GTCC4 Lusso	17-20		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Ferrari	LaFerrari	14-15		5003 (Program first)	9011	1096	1096	No tools needed
Ferrari	Portofino	19-22		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Ferrari	Roma	21-22		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Ferrari	SF90	21-22		5001 (Program first) or 5003 (Program first)	9017	1096	1096	No tools needed
Fiat	124 Spider Abarth	17-20	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Fiat	500	12-19		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Fiat	500L	14-20		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Fiat	500X	16-17	7008HP	5001 (Program first) or 5003 (Program first)	5775	VS90	VS90	Auto-relearn
Fiat	500X	18-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Fisker	Karma	10-12			NEW	VS1010	VS1010	Dealer OBD only
Ford	Bronco	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS950	VS950	Trigger required
Ford	Bronco Sport	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	C-Max	13-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Crown Victoria	08-11	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	E Series	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048-HP	Banded	NO	Trigger required
Ford	E-250 / E-350 van	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048-HP	Banded	NO	Trigger required
Ford	E Series	10-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	E Series SRW	21-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	E Series DRW (RV-prepped)	21-23	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9291	VS241	VS241	Trigger required
Ford	EcoSport	18-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Ford	Edge	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Edge	11-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Edge	15-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Escape	05-08	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Escape	09-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Escape	20-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	E-Transit	22-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Expedition	03-04	7004**	5001 (Program first) or 5003 (Program first)	9096	1060K	NO	Trigger required
Ford	Expedition	05-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	Discontinued	1060K	NO	Trigger required
Ford	Expedition	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Expedition	11-17	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Expedition	18-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Expedition	23-24			NEW	VS20	VS20	Trigger required
Ford	Explorer	02-05	7004**	5001 (Program first) or 5003 (Program first)	9096	1060K	NO	Trigger required
Ford	Explorer Sport Trac	07-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Explorer	06-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Explorer	11-15	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Explorer	16-19	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Explorer	20-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Explorer	25			NEW	VS20	VS20	Trigger required
Ford	F-150 Light Duty (6-Lug)	07-08	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	F-150 Heavy Duty (7-Lug)	07-08	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048-HP	Banded	NO	Trigger required
Ford	F-150	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	F-150	15-20	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	F-150	21-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS950	VS950	Trigger required
Ford	F-150	24			NEW	VS950	VS950	Trigger required
Ford	F-250 / F-350	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048-HP	Banded	NO	Trigger required
Ford	F-250 / F-350	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	F-250 / F-350 (snap-in)	17-22	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	F-250 / F-350 (SRW)	23-24			NEW	VS20	VS20	Trigger required
Ford	F-350 Dually (clamp-in)	17-22	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9291	VS241	VS241	Trigger required
Ford	F-350 DRW (all steel wheels)	23			NEW	VS241	VS241	Trigger required
Ford	F-350 DRW (front alloy wheel)	23			NEW	VS20	VS20	Trigger required
Ford	F-350 DRW (rear alloy wheel)	23			NEW	VS241	VS241	Trigger required
Ford	F-250 / F-350 Trailer TPMS	17-20			9189	VS240MC	VS240MC	No tools needed
Ford	Fiesta	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Flex	09-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Flex	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Focus	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Focus (non-RS)	10-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Focus RS (clamp-in)	16-18	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS240MC	VS240MC	Trigger required
Ford	Focus RS (snap-in)	16-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS20	VS20	Trigger required
Ford	Freestar	06-07	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Fusion	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Fusion	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Fusion	17-20	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	GT	17-22	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9291	VS240MC	VS240MC	Auto-relearn
Ford	Maverick	22-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Mustang	07-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Mustang (snap-in)	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Mustang (clamp-in)	13-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS925C	VS925C	Trigger required
Ford	Mustang	15-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Mustang (clamp-in)	15-23	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9291	VS240MC	VS240MC	Auto-relearn
Ford	Mustang	24			NEW	VS20	VS20	Trigger required
Ford	Mustang (clamp-in)	24			NEW	VS240MC	VS240MC	Trigger required
Ford	Mustang Mach-E	21-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Auto-relearn
Ford	Police Interceptor sedan	13-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	13-15	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Police Interceptor Utility	16-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Ranger	07-11	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Ranger	19-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Taurus	08-10	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Taurus	11-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Taurus X	08-09	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Trigger required
Ford	Trailer TPMS	17-24			9189	VS240MC	VS240MC	No tools needed
Ford	Transit Connect	10-18	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Transit Connect	19-23	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Transit (SRW)	15-19	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required
Ford	Transit (SRW)	20-24	7003A, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9280	VS20	VS20	Trigger required
Ford	Transit (DRW)	20-24	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9291	VS241	VS241	Trigger required
Freightliner	Sprinter (SRW)	07-13		5002 (Program first) or 5003 (Program first)	1042	1098K	1098K	Trigger required
Freightliner	Sprinter (SRW)	14-17		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
Freightliner	Sprinter (SRW)	18		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
Freightliner	Sprinter (SRW)	19-21		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
Genesis	G70	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	Auto-relearn
Genesis	G80	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5510	7020K	VS70	Auto-relearn
Genesis	G80	21-23	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	Auto-relearn
Genesis	G90	17-22	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	Auto-relearn
Genesis	G90	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	1100K	VS40	Auto-relearn
Genesis	GV60	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	1100K	VS40	Auto-relearn
Genesis	GV70	22-24			NEW	7020K	VS70	Auto-relearn
Genesis	GV80	21-24	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	Auto-relearn
GMC	Acadia	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
GMC	Acadia	09-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Acadia	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia Limited	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Acadia	17	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9773	VS20	VS20	Trigger required
GMC	Acadia	18-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Acadia	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Canyon	07-12	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
GMC	Canyon	15-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Canyon	17-19	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Canyon	20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Canyon	21-22			2346	VS20	VS20	Auto-relearn
GMC	Canyon	23-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Envoy	06-09	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
GMC	Hummer EV	22-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
GMC	Savana	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
GMC	Savana	10-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Savana (SRW)	17-24	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 1500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 1500	18	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra Limited	19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra 1500	19-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 Limited	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra 1500 (facelifted)	22-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 2500/3500	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Sierra 2500/3500	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Sierra 2500/3500	18-19	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	20-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6561	VS20	VS20	Trigger required
GMC	Sierra HD (SRW)	24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
GMC	Sierra 3500HD DRW (Front alloy wheel)	20-23		5001 (Program first) or 5003 (Program first)	7659	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front alloy wheel)	24		5003 (Program first)	7624	DA543E	DA543E	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Front steel wheel)	24		5003 (Program first)	8424	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	20-23	7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	Trigger required
GMC	Sierra 3500HD DRW (Rear wheels)	24		5003 (Program first)	8424	2030K	VS40	Trigger required
GMC	Sierra Trailer TPMS	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
GMC	Terrain	10-14	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Terrain	15-17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Terrain	18-21	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Terrain	22-24	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	2346	VS20	VS20	Trigger required
GMC	Trailer TPMS	21-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8463	2030K	VS40	No tools needed
GMC	Yukon (all)	04		5002 (Program first) or 5003 (Program first)	9115	1070K	NO	Trigger required
GMC	Yukon (all)	05-06	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9107	1070K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinue	2020K	NO	Trigger required
GMC	Yukon	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinue	2020K	NO	Trigger required
GMC	Yukon 2500	07	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
GMC	Yukon	07-16	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon 2500	07-13	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
GMC	Yukon	17	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS20	VS20	Trigger required
GMC	Yukon	18-20	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	6164	VS20	VS20	Trigger required
GMC	Yukon	21-24		5003 (Program first)	3166	VS20	VS20	Auto-relearn
Honda	Accord	08-12	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	Civic	08-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	CR-V	07-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	CR-V	12-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5511	7020K	VS70	OBDII required
Honda	CR-Z	11-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Crosstour	10-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5511	7020K	VS70	OBDII required
Honda	Element	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Honda	Element	09-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Fit	08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Honda	Fit	09-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Insight	10-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey EX, EX-L, LX	07	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Honda	Odyssey EX, EX-L, LX	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2045K or 2000K	None or 1096	OBDII required
Honda	Odyssey Touring	05-07	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Odyssey Touring	08-10	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Odyssey and Touring	11-17	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1212	2045K	NO	OBDII required
Honda	Odyssey	18-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Odyssey	21-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Passport	19-21		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Passport	22-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Pilot (Steel Wheels)	05-08	7002A or 7007HP		1059	2000K	1097	Auto-relearn
Honda	Pilot (Alloy Wheels)	05-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Pilot (Alloy Wheels)	09-15	7002A or 7007HP		1209	1100K	NO	Auto-relearn
Honda	Pilot (Steel Wheels)	09-15	7002A or 7007HP		1219	1100K	NO	Auto-relearn
Honda	Pilot	16-22		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Pilot	23-25		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	Prologue	24			3166	VS20	VS20	Auto-relearn
Honda	Ridgeline (Steel Wheels)	06-08	7002A or 7007HP		1059	2000K	1097	Auto-relearn
Honda	Ridgeline (Alloy Wheels)	06-08	7002A or 7007HP		1057	2000K	1096	Auto-relearn
Honda	Ridgeline	09-14	7002A or 7007HP		1057	2045K or 2000K	None or 1096	Auto-relearn
Honda	Ridgeline	17-20		5003 (Program first)	3751	7000K	VS70	Auto-relearn
Honda	Ridgeline	21-24		5003 (Program first)	5517	VS20	VS20	Auto-relearn
Honda	S2000	08-09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1208	1100K	NO	OBDII required
Hummer	H2	09-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Hummer	H3	06-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Hummer	H3T	09-10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Hyundai	Accent	08-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Accent	12-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Accent	14	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Accent	15-22	7008HP	5001 (Program first) or 5003 (Program first)	5510	7020K	VS70	OBDII required
Hyundai	Azera	07-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
Hyundai	Azera (315MHz)	12-14		5002 (Program first) or 5003 (Program first)	1233	2040K	VS965	OBDII required
Hyundai	Azera (433MHz)	14-17		5001 (Program first) or 5003 (Program first)	NEW	2040K	VS965	OBDII required
Hyundai	Elantra	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
Hyundai	Elantra	11-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1222	2040K	VS965	OBDII required
Hyundai	Elantra	14-16	7007HP	5002 (Program first) or 5003 (Program first)	3205	2040K	VS965	OBDII required
Hyundai	Elantra	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Elantra and N-Line	21-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Elantra N	22-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Elantra N	24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	1100K	VS40	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Hyundai	Elantra Touring	09-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	1050K or 7020K	None or VS70	Auto-relearn
Hyundai	Elantra GT	13-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Elantra GT	18-20	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Entourage	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1028	2000K	1096	OBDII required
Hyundai	Equus	11-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Equus	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Genesis Sedan	09-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Genesis Sedan	15-16	7008HP	5001 (Program first) or 5003 (Program first)	5510	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	10-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Genesis Coupe	13-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	ioniq	17-22	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	ioniq 5	22-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	ioniq 5 N	25	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	ioniq 6	23	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	ioniq 6	24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Kona	18-23	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Kona	24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Nexo	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Palisade	20-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Santa Cruz	22-25	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Santa Fe	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1028	2000K	1096	OBDII required
Hyundai	Santa Fe	09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
Hyundai	Santa Fe	10-12	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	VS1010	VS1010	OBDII required
Hyundai	Santa Fe	13-18	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Santa Fe XL	19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Santa Fe Sport	18	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Santa Fe (non-XL)	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	07	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Hyundai	Sonata GLS/Limited	08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Hyundai	Sonata SE	08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Sonata	09-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Sonata	11-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required
Hyundai	Sonata	13-14	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Sonata Hybrid	15	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
Hyundai	Sonata (non-hybrid)	15	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	16-19	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Sonata	20-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Sonata N-Line	21-24	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Tiburon	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Hyundai	Tucson	06-09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
Hyundai	Tucson	10-13	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
Hyundai	Tucson	14-15	7007HP	5002 (Program first) or 5003 (Program first)	2510	2040K	VS965	OBDII required
Hyundai	Tucson	16-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
Hyundai	Tucson	22-25	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Hyundai	Veloster	12-17	7007HP	5002 (Program first) or 5003 (Program first)	9505	VS950	VS950	OBDII required
Hyundai	Veloster	19-22	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Venue	20-24	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
Hyundai	Veracruz	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1028	2000K	1096	OBDII required
Hyundai	Veracruz	09-12	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
INEOS	Grenadier	24	7008HP	5001 (Program first) or 5003 (Program first)	5559	7020K	VS70	OBDII required
Infiniti	EX	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Infiniti	EX (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	FX	03-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Infiniti	FX	08	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Infiniti	FX	09-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Infiniti	FX (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	G35	04-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Infiniti	G35 Coupe (Post Aug. 2006)	07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Infiniti	G35 Sedan	07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Infiniti	G	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Infiniti	G (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	JX	13	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Infiniti	M	03-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Infiniti	M	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Infiniti	M (Post March 2010)	10-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q40	15	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q45	03-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Infiniti	Q50	14-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	5558	7020K	VS70	OBDII required
Infiniti	Q50	16-23	7002A or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Infiniti	Q60	14-15	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	Q60	17-22	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Infiniti	Q70	14-19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX30	17-19	7001HP or 7007HP	5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
Infiniti	QX50	14-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX50	19-22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Infiniti	QX50	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Infiniti	QX55	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Infiniti	QX55	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Infiniti	QX56	04-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Infiniti	QX56	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Infiniti	QX56 (Post March 2010)	10	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX56	11-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX60	14-20	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Infiniti	QX60 (snap-in)	20	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5564	VS20	VS20	OBDII required
Infiniti	QX60	22-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Infiniti	QX70	14-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Infiniti	QX80	17	7008HP	5001 (Program first) or 5003 (Program first)	1382	1100K	NO	OBDII required
Infiniti	QX80	18-22	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	NO	OBDII required
Infiniti	QX80	23-24	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	VS312	OBDII required
Infiniti	QX80	25	7006HPR	5002 (Program first) or 5003 (Program first)	TBD	VS15	VS15	OBDII required
Isuzu	Ascender	06-08	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Isuzu	I-series pickup	07-08	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	9131	1110K	NO	Trigger required
Isuzu	Rodeo	04	7008HP	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Dealer OBD only
Jaguar	E-Pace	18-21	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	E-Pace	22-24	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.
 Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos
 Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Jaguar	F-Pace	17-21	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	F-Pace	22-24	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	F-Type (315MHz)	14-15			1045	7020K	VS70	Auto-relearn
Jaguar	F-Type (433MHz Export)	14			1046	1050K	NO	Auto-relearn
Jaguar	F-Type (433MHz)	15-24	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (clamp-in)	19-22	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	I-Pace (snap-in)	22-24	7008HP	5001 (Program first) or 5003 (Program first)	5077	VS20	VS20	Auto-relearn
Jaguar	X-Type (315MHz)	08		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	X-Type (433MHz Export)	08			1046	1050K	NO	Auto-relearn
Jaguar	XE	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XF (315MHz)	09-16		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XF (433MHz Export)	09-15			1046	1050K	NO	Auto-relearn
Jaguar	XF (433MHz)	16-24	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XJ (315MHz)	06-09		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	10-11			1045	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz Export)	06-11			1046	1050K	NO	Auto-relearn
Jaguar	XJ (315MHz)	12-16			1045	1050K or 7020K	None or VS70	Auto-relearn
Jaguar	XJ (433MHz Export)	12-14			1046	1050K	NO	Auto-relearn
Jaguar	XJ (433MHz)	15-19	7008HP	5001 (Program first) or 5003 (Program first)	5276	7020K	VS70	Auto-relearn
Jaguar	XK (315MHz)	07-15		5002 (Program first) or 5003 (Program first)	1055	1050K	NO	Auto-relearn
Jaguar	XK (433MHz Export)	07-15			1046	1050K	NO	Auto-relearn
Jeep	Cherokee	14-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
Jeep	Cherokee	19-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
Jeep	Commander	06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Commander	07	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Jeep	Commander	08-10	7004	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Compass	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Compass	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Compass (315MHz)	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz Export)	13-14			9481	VS950	VS950	Auto-relearn
Jeep	Compass (433MHz)	17-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Gladiator	20-21		5001 (Program first) or 5003 (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Gladiator (built on or after 6/7/2021)	21-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee	02-04	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Jeep	Grand Cherokee	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Grand Cherokee	07	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	08-10	7004	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee	11-15		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Grand Cherokee	16	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS90	VS90	Auto-relearn
Jeep	Grand Cherokee (non-L)	17-21	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (WK)	22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee L	21		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee (New) and L	22-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Grand Cherokee SRT8	12-15		5001 (Just relearn) or 5003 (Program first)	9214	9066K	9066K	Auto-relearn
Jeep	Grand Cherokee SRT	16-21	7008HP	5001 (Program first) or 5003 (Program first)	2495	7020K	VS70	Auto-relearn
Jeep	Grand Wagoneer	22-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Liberty	04	7004	5001 (Program first) or 5003 (Program first)	9028	1080K	NO	Trigger required
Jeep	Liberty	05-06	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Liberty	07-10	7001HP or 7007HP		9066	9066K	9066K	Auto-relearn
Jeep	Liberty	10-12	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Liberty (433MHz Export)	07-09	7004	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Liberty (433MHz Export)	10-12			9481	VS950	VS950	Auto-relearn
Jeep	Patriot	07-10	7001HP or 7007HP		1051	1050K	NO	Auto-relearn
Jeep	Patriot	11-12	7001HP or 7007HP		1051	7000K	VS70	Auto-relearn
Jeep	Patriot	13-17	7001HP-R or 7007HP		9308	VS950	VS950	Auto-relearn
Jeep	Patriot (433MHz Export)	12-14			9481	VS950	VS950	Auto-relearn
Jeep	Renegade	15-16	7008HP	5001 (Program first) or 5003 (Program first)	5775	VS90	VS90	Auto-relearn
Jeep	Renegade	17-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5777	VS20	VS20	Auto-relearn
Jeep	Wagoneer	22-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
Jeep	Wrangler	07-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9066	9066K	9066K	Auto-relearn
Jeep	Wrangler (433MHz Export)	08-10	7004	5001 (Program first) or 5003 (Program first)	1043	9066K	9066K	Auto-relearn
Jeep	Wrangler	10-12	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	9308	VS950	VS950	Auto-relearn
Jeep	Wrangler (433MHz Export)	10-12		5001 (Program first) or 5003 (Program first)	9481	VS950	VS950	Auto-relearn
Jeep	Wrangler (JK)	13-18		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler (JL)	18-20		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
Jeep	Wrangler	21		5001 (Program first) or 5003 (Program first)	4665	VS950	VS950	Auto-relearn
Jeep	Wrangler (built on or after 6/7/2021)	21-24		5003 (Program first)	3996	VS20	VS20	Auto-relearn
KIA	Amanti	07-08	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
KIA	Amanti	09	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1058	2000K	1096	OBDII required
KIA	Borrego	09-11	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1029	2040K	NO	OBDII required
KIA	Cadenza	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
KIA	Cadenza	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
KIA	Carnival	22-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	Carnival	25			TBD	VS20	VS20	
KIA	EV6 (snap-in)	22-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	EV6 GT (clamp-in)	23-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	1100K	VS40	
KIA	EV9	24			TBD	VS20	VS20	
KIA	Forte	10-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required
KIA	Forte	14-15	7007HP	5002 (Program first) or 5003 (Program first)	2510	2040K	VS965	OBDII required
KIA	Forte	16-18	7007HP	5002 (Program first) or 5003 (Program first)	3205	2040K	VS965	OBDII required
KIA	Forte	19-24		5001 (Program first) or 5003 (Program first)	NEW	1100K	NO	OBDII required
KIA	K4	25			TBD	VS20	VS20	
KIA	K5 (snap-in)	21-24	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	K5 GT (clamp-in)	21-24	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
KIA	K900	15-17			NEW	VS950	VS950	OBDII required
KIA	K900	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	9237	VS20	VS20	OBDII required
KIA	Magentis	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
KIA	Niro	17-22	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
KIA	Niro	23-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
KIA	Optima	06-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1068	2000K	1096	OBDII required
KIA	Optima	11-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5507	7020K	VS70	OBDII required
KIA	Optima	14-15	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
KIA	Optima Hybrid	16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5508	7020K	VS70	OBDII required
KIA	Optima non-hybrid	16	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required
KIA	Optima	17-20	7008HP	5001 (Program first) or 5003 (Program first)	5523	7020K	VS70	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Table with columns: Make, Model, Model Year Range, Dill REDI-Sensor Sensor, Dill 5000-Series Sensor, Dill OE Sensor, Dill OE Kit, Dill OE Valve Stem, Simplified Relearn. Rows include vehicles from KIA, Lamborghini, Land Rover, and Lexus.

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dilvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Mazda	6	08-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	1050K	NO	Auto-relearn
Mazda	6	10-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	6	18-20	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	6	21	7006HPR	5002 (Program first) or 5003 (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	MX-30	22-23	7006HPR	5002 (Program first) or 5003 (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	MX-5 Miata	06-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	1050K	NO	Auto-relearn
Mazda	MX-5 Miata	10-15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	18-20	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	MX-5 Miata	21-24	7006HPR	5002 (Program first) or 5003 (Program first)	5310	VS20	VS20	Auto-relearn
Mazda	RX-8	04	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	1130K	NO	Auto-relearn
Mazda	RX-8	05-10	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	1050K	NO	Auto-relearn
Mazda	RX-8	10-11	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	1056	7020K	VS70	Auto-relearn
Mazda	Tribute	05-08	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	1048	Banded	NO	Auto-relearn
Mazda	Tribute	09-11	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Auto-relearn
McLaren	MP4-12c	12-14		5003 (Program first)	9011	1096	1096	Auto-relearn
McLaren	P1	14-15		5003 (Program first)	9011	1096	1096	Auto-relearn
McLaren	570GT	17-18		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
McLaren	570S	16		5003 (Program first)	9011	1096	1096	Auto-relearn
McLaren	570S	19-20		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
McLaren	650S	15-16		5003 (Program first)	9011	1096	1096	Auto-relearn
McLaren	675LT	16		5003 (Program first)	9011	1096	1096	Auto-relearn
McLaren	720S	18-20		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
M-Benz	A-Class	19-22		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	AMG GT 2-dr	16-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	AMG GT 2-dr	24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	AMG GT 4-dr	19-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	B-Class	14-17		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	C-Class	08-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	C-Class	15-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	C-Class coupe	22-23		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	C-Class sedan	22-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	CL-Class	01-06		5003 (Program first)	9004	1090K	1094	No tools needed
M-Benz	CL-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	CL-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLA-Class	14-19		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	CLA-Class	20-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	CLK-Class	08-09		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	06-11	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	CLS-Class	12-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	CLS-Class	15-18		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	CLS-Class	19-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	E-Class	03-06		5003 (Program first)	9004	1090K	1094	No tools needed
M-Benz	E-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	E-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	E-Class	15-16		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	E-Class 2dr.	17		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	E-Class sedan and wagon	17		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	E-Class	18-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	EQB	22-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	EQE sedan	23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	EQE SUV	23-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	EQS sedan	22-24		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	EQS SUV	23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	G-Class	07-15		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	G-Class	16-18		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	G-Class	19-22		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	GL-Class	07-09		5001 (Program first) or 5003 (Program first)	1049	1040K	1040K	No tools needed
M-Benz	GL-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	GL-Class	15-16		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLA-Class	15-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLA-Class	21-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	GLB-Class	20-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	GLC-Class (X253)	16-23		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLC-Class (X254)	23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	GLE-Class	16-19		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLE-Class	20-24		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	GLK-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	GLK-Class	15		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLS-Class	17-19		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	GLS-Class	20-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	Maybach S-Class	16-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	Maybach S-Class	21-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	Maybach GLS-Class	21-23		5001 (Program first) or 5003 (Program first)	9077	1096	1096	No tools needed
M-Benz	Metris	16-23		5001 (Just relearn) or 5003 (Program first)	9398	VS20	VS20	No tools needed
M-Benz	ML-Class	07-09		5001 (Program first) or 5003 (Program first)	1049	1040K	1040K	No tools needed
M-Benz	ML-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	ML-Class	15		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	R-Class	07-09		5001 (Program first) or 5003 (Program first)	1049	1040K	1040K	No tools needed
M-Benz	R-Class	10-12		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	S-Class	01-06		5003 (Program first)	9004	1090K	1094	No tools needed
M-Benz	S-Class	07-09	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	S-Class	10-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	S-Class	15-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	S-Class 2dr.	21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	S-Class sedan	21-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	SL-Class	03-05		5003 (Program first)	9004	1090K	1094	No tools needed
M-Benz	SL-Class	06-12	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	SL-Class	13-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	SL-Class	15-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	SL-Class	22-23		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	No tools needed
M-Benz	SLC-Class	17-20		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	SLK-Class	08-14		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
M-Benz	SLK-Class	15-16		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	No tools needed
M-Benz	SLR McLaren (315 MHz)	05-07		5003 (Program first)	9004	1090K	1094	No tools needed
M-Benz	SLR McLaren (433 MHz)	05-07		5003 (Program first)	9001	1090K	1094	No tools needed
M-Benz	SLR McLaren (315 MHz)	08-09	7003A or 7007HP		1054	1040K	1040K	Trigger required
M-Benz	SLR McLaren (433 MHz)	08-09		5001 (Program first) or 5003 (Program first)	1049	1040K	1040K	No tools needed
M-Benz	SLS AMG	11-15		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Nissan	Juke SV & SL (w/ I-Key-- 7/10 - 7/11)	11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key-- 7/11 - 9/11)	11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Juke Base (w/out I-Key--Post 3/12)	12-15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Nissan	Juke (w/ I-Key--Post 2/12)	12-15	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Kicks	16-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Kicks	18-20	7008HP	5001 (Program first) or 5003 (Program first)	4750	VS30	VS30	OBDII required
Nissan	Kicks	21-24	7008HP	5001 (Program first) or 5003 (Program first)	4750	VS15	VS15	OBDII required
Nissan	Kicks	25			TBD	VS15	VS15	
Nissan	Leaf	11	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Leaf	12-13	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Leaf	13-17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Leaf	18-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Nissan	Leaf	21-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Nissan	Maxima	07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Maxima	07-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Maxima	12-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Maxima	16-19	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Nissan	Maxima (snap-in)	19-23	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5564	VS20	VS20	OBDII required
Nissan	Murano	03-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Nissan	Murano	07-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Murano (Post Nov. 2011)	12-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Nissan	Murano	15-19	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Nissan	Murano (snap-in)	19-24	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5564	VS20	VS20	OBDII required
Nissan	NV200	13-17	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	NV200	18-21	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	NV 1500/2500HD/3500HD	12-21		5002 (Program first) or 5003 (Program first)	9342	2030K	NO	OBDII required
Nissan	Pathfinder	03-04	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Nissan	Pathfinder (w/ Steel wheels)	04	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9069	1130K	NO	OBDII required
Nissan	Pathfinder	05-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Pathfinder	07-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Pathfinder	13-19	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5556	7020K	VS70	OBDII required
Nissan	Pathfinder (snap-in)	19-20	7001HP or 7007HP	5001 (Program first) or 5003 (Program first)	5564	VS20	VS20	OBDII required
Nissan	Pathfinder	22-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	OBDII required
Nissan	Qashqai	17-23	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Nissan	Quest (w/ Steel wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9069	1130K	NO	OBDII required
Nissan	Quest (w/ Alloy wheels)	04-06	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Quest	07-09	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Quest	11-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1216	1100K	NO	OBDII required
Nissan	Quest	17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1344	VS30	VS30	OBDII required
Nissan	Rogue	08-11	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Rogue	12-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Nissan	Rogue Select	14-15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Rogue clamp-in (433 MHz)	14-16	7008HP	5001 (Program first) or 5003 (Program first)	5559	7020K	VS70	OBDII required
Nissan	Rogue snap-in	16-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Nissan	Rogue	21-24	7006HPR	5003 (Program first)	NEW	VS20	VS20	OBDII required
Nissan	Rogue Sport	17-22	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	5661	VS90	VS90	OBDII required
Nissan	Sentra (w/ Alloy wheels)	07-08	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Sentra	07-12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Sentra (> 1/12)	12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Nissan	Sentra (w/out I-Key)	13-16	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Sentra (w/out I-Key)	17-19	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Sentra (w/ I-Key)	13-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Sentra (w/ I-Key)	17-19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Sentra	20-23	7006HPR	5002 (Program first) or 5003 (Program first)	4761	VS15	VS15	OBDII required
Nissan	Sentra	24			TBD	VS15	VS15	
Nissan	Titan (w/ Alloy wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Titan (w/ Steel wheels)	04-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9069	1130K	NO	OBDII required
Nissan	Titan	07-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Titan	15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Titan XD	16	7008HP	5001 (Program first) or 5003 (Program first)	1382	1100K	NO	OBDII required
Nissan	Titan (all)	17-23	7008HP	5001 (Program first) or 5003 (Program first)	1382	1100K	NO	OBDII required
Nissan	Versa	07-11	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Versa Sedan	12	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	13-16	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Sedan S and SV	17	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan	18	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Sedan SL	13-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Versa Sedan SL	17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa (key-in ignition)	19	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa (push-button ign.)	19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa	20-22	7008HP	5001 (Program first) or 5003 (Program first)	4750	VS30	VS30	OBDII required
Nissan	Versa	23-24	7008HP	5001 (Program first) or 5003 (Program first)	4750	VS15	VS15	OBDII required
Nissan	Versa Hatchback (Post Jan. 2012)	12-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	1100K	NO	OBDII required
Nissan	Versa Note S/SR/SV	14-16	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Versa Note S/SR/SV	17	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note (w/out I-Key)	18-19	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	5362	VS90	VS90	OBDII required
Nissan	Versa Note SL	14-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5557	7020K	VS70	OBDII required
Nissan	Versa Note SL	17	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Versa Note (w/ I-Key)	18-19	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	5163	VS90	VS90	OBDII required
Nissan	Xterra	03-04	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9064	1080K	NO	OBDII required
Nissan	Xterra	05-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9161	1080K	NO	OBDII required
Nissan	Xterra (w/ Steel wheels)	05-07	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9069	1130K	NO	OBDII required
Nissan	Xterra (<10/13)	08-13	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Xterra	13-14	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	5555	7020K	VS70	OBDII required
Nissan	Xterra	15	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9204	2030K	NO	OBDII required
Nissan	Z	23-24	7006HPR	5002 (Program first) or 5003 (Program first)	1375	1100K	VS312	OBDII required
Plymouth	Prowler	97-01			8004	1077K	NO	Dealer OBD only
Pontiac	G3	09	7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	OBDII required
Pontiac	G5	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G5	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G6 (Pre-10/15/07)	08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	G6 (Post-10/15/07)	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	G8	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Pontiac	Grand Prix	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Grand Prix	08	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Pontiac	Montana	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	9158	1070K	NO	Trigger required
Pontiac	Solstice	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Torrent	07-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Pontiac	Vibe	08-10	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Pontiac	Wave	08-10	7006HPR or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	OBDII required
Porsche	911	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	911 Turbo	09		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	911 (non-Turbo)	09-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	911 Turbo	10-11		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	911	12-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	911	17-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	918 Spyder	15		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Boxster	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Boxster	09-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Boxster	12-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	718 Boxster	17-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Carrera GT	04-06		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayenne	03-06			9005	1090K	1092	No tools needed
Porsche	Cayenne	08-10		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayenne	11-14		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Cayenne	15-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Cayman	06-08		5003 (Program first)	9001	1090K	1092	No tools needed
Porsche	Cayman	09-10		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Cayman	11-16		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	718 Cayman	17-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Macan	15-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Panamera	10-11		5003 (Program first)	9011	1090K	1092	No tools needed
Porsche	Panamera	12-13		5003 (Program first)	9011	1096	1096	No tools needed
Porsche	Panamera	14-23		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
Porsche	Taycan	20-24		5001 (Program first) or 5003 (Program first)	9018	1096	1096	Auto-relearn
RAM	1500, 2500, 3500 pickup	11-13		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
RAM	1500, 2500, 3500 SRW	14-18		5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	19-20	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	1500 Classic (DS)	21-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	1500 (DT)	19-24		5001 (Program first) or 5003 (Program first)	3199	VS950	VS950	Auto-relearn
RAM	2500, 3500 SRW	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	14-18	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	6815	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Steel Wheel Sensor)	19-24		5001 (Program first) or 5003 (Program first)	6896	VS65	VS65	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	14-18		5001 (Program first) or 5003 (Program first)	6829	VS35	VS35	Auto-relearn
RAM	3500 DRW (Outer Alloy Wheel Sensor)	19-24		5001 (Program first) or 5003 (Program first)	6846	VS35	VS35	Auto-relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	14-18			6825	VS65	VS65	Auto-relearn
RAM	3500 DRW (Inner Rear Wheel Sensor)	19-24			6854	VS65	VS65	Auto-relearn
RAM	Ram 4500, 5500 (Outer Steel Wheel Sensor)	19-24			6924	VS969	VS969	Auto-relearn
RAM	Ram 4500, 5500 (Outer Alloy Wheel Sensor)	19-24			6935	VS35	VS35	Auto-relearn
RAM	Ram 4500, 5500 (Inner Rear Wheel Sensor)	19-24			NEW	VS969	VS969	Auto-relearn
RAM	Trailer TPMS	19-24			NEW	2030K (0.453)	VS40'	No tools needed
RAM	Cargo Van (CV)	12-15		5001 (Just relearn) or 5003 (Program first)	9398	VS950	VS950	Auto-relearn
RAM	Dakota	11	7001HP-R or 7007HP	5002 (Program first) or 5003 (Program first)	9308	VS950	VS950	Auto-relearn
RAM	Promaster	14-21		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
RAM	Promaster	22-23	7008HP	5001 (Program first) or 5003 (Program first)	2495	7020K	VS70	Auto-relearn
RAM	Promaster City	15-22		5001 (Just relearn) or 5003 (Program first)	9214	1100K	VS40	Auto-relearn
Rivian	R1S	22-24		5003 (Program first)	7420	1096	1096	Auto-relearn
Rivian	R1T	22-24		5003 (Program first)	7420	1096	1096	Auto-relearn
Rolls Royce	Cullinan	19-21		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Auto-relearn
Rolls Royce	Dawn	16-17		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Dawn	18-21		5001 (Program first) or 5003 (Program first)	9017	1096	1096	Auto-relearn
Rolls Royce	Drophead Coupe	09-14		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn
Rolls Royce	Drophead Coupe	15-17		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Ghost	10-11		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn
Rolls Royce	Ghost (Post Sept. 2010)	11-18		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Ghost	22		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Auto-relearn
Rolls Royce	Phantom	07-11		5003 (Program first)	1027	1090K	1092 or 1094	Auto-relearn
Rolls Royce	Phantom	12-16		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Rolls Royce	Phantom	17-20		5001 (Program first) or 5003 (Program first)	9077	1100K	VS40	Auto-relearn
Rolls Royce	Wraith	14-18		5001 (Program first) or 5003 (Program first)	9012	1096	1096	Auto-relearn
Saab	9-3	03-07		5001 (Program first) or 5003 (Program first)	9078	2010K	NO	Auto-relearn
Saab	9-3	08-11		5001 (Program first) or 5003 (Program first)	9159	2010K	NO	Auto-relearn
Saab	9-4x	11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Saab	9-5	08-09		5001 (Program first) or 5003 (Program first)	9159	2010K	NO	Auto-relearn
Saab	9-5	10-11	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Saab	9-7X	07-09	7001HP or 7007HP	5002 (Program first) or 5003 (Program first)	9116	1070K	NO	Trigger required
Saturn	Astra	08-09		5001 (Program first) or 5003 (Program first)	9078	2010K	NO	Auto-relearn
Saturn	Aura (<10/14/07)	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Aura (>10/14/07)	08-09	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Saturn	Outlook	07-08	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Outlook	09-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Saturn	Sky	08-09	7001HP or 7007HP	5002 (Just relearn) or 5003 (Program first)	Discontinued	1050K	NO	Trigger required
Saturn	Vue	08-10	7001HP-R, 7006HPR, or 7007HP	5002 (Just relearn) or 5003 (Program first)	9153	VS950	VS950	Trigger required
Scion	FR-S	13-16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1218	1100K	NO	OBDII required
Scion	iM	16	7003A or 7007HP	5002 (Program first) or 5003 (Program first)	1218	1100K	NO	OBDII required
Scion	iQ	12-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	tC	07-16	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	xB	08-15	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Scion	xD	08-14	7002A or 7007HP	5002 (Program first) or 5003 (Program first)	1204 (OE),	1100K (OE), 2	None (OE), 1096	OBDII required
Smart	Fortwo	08-15		5001 (Just relearn) or 5003 (Program first)	9214	2030K	9066K	No tools needed
Smart	Fortwo	16-19	7008HP	5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	No tools needed
Subaru	Ascent	19-24	7005HPR or 7008HP	5001 (Program first) or 5003 (Program first)	8023	VS20	VS20	OBDII required

Verify Model Year by checking the 10th digit in the VIN: 8 = 2008MY, 9 = 2009MY, A = 2010MY, B = 2011MY, etc.

Visit dillvalves.com for vehicle look-ups containing parts, pictures, relearns and training videos

Need Additional Help? Call 800-815-3455, option 3 for technical support

DILL TPMS APPLICATIONS CHART ©



(Row Color designates the required replacement parts kit for the OE sensor.)

Make	Model	Model Year Range	Dill REDI-Sensor Sensor	Dill 5000-Series Sensor	Dill OE Sensor	Dill OE Kit	Dill OE Valve Stem	Simplified Relearn
Volvo	XC60	10-13	7004	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC60	14-17		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC70	05-07	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC70	08-10	7004	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	XC70	10-13	7004	5001 (Program first) or 5003 (Program first)	1044	7020K	VS70	Auto-relearn
Volvo	XC70 (clamp-in)	14-16		5001 (Program first) or 5003 (Program first)	5134	7020K	VS70	Auto-relearn
Volvo	XC90 (315 MHz)	05-08	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	2010K	NO	Auto-relearn
Volvo	XC90 (433 MHz)	08	7004	5001 (Program first) or 5003 (Program first)	1044	1050K	NO	Auto-relearn
Volvo	XC90 (315 MHz)	08-14	7003A or 7006HPR	5002 (Program first) or 5003 (Program first)	9156	VS950	VS950	Trigger required
Volvo	XC90 (Direct TPMS)	16-17		5001 (Program first) or 5003 (Program first)	NEW	VS20	VS20	Auto-relearn
VPG	MV-1	11-13	7001HP-R, 7006HPR, or 7007HP	5002 (Program first) or 5003 (Program first)	9315	VS950	VS950	Trigger required

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year. **PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.**